

Three Lakes Water Association

P.O. Box 24, Snohomish, WA 98291-0024

(360) 568-8022 www.3lwa.org

October 11, 2024

In order to help reduce the public's potential exposure to lead in drinking water, it was determined by the USEPA that all potable water systems create a lead service line inventory. The inventory is required to include material information on both the water system owned portion and privately owned portion of all service lines served by that water system purveyor and to be publicly available.

We reviewed 50 years of service documentation, as well as performed excavation in the field to confirm the material type at each water system owned portion of the service line.

Even though the Association's jurisdiction ends at the meter, the USEPA requires material information on the privately owned portion of the member's service line to be reported as part of this new rule. Therefore, the Association mailed out a survey to those members whose homes were built after the state ban of lead in drinking water, asking for any material information on their private service line on the downstream side of the meter. Many members responded with material information that was added to the inventory which also helped to reduce the overall cost to the membership in order to comply with this regulation.

The Association reports that **NO LEAD** Service Lines were discovered in the inventory on the water system owned portion of the service lines.

The Association's service line inventory was submitted to the Department of Health on October 1st, 2024, prior to the October 16th, 2024 deadline.

As this is an ongoing effort to continue to acquire material information on the members' private service line for those that have not yet been provided, please complete the survey below if you have any information on your private service line material type and return it to the Association, or you may call the office at the above phone number to provide the information.

We appreciate your cooperation in assisting us with this federal requirement.

Three Lakes Water Association

Three Lakes Water Association

P.O. Box 24, Snohomish, WA 98291-0024
(360) 568-8022 www.3lwa.org

October 11, 2024

Dear Member,

You may have recently heard more news about lead in drinking water and the potential health risks it can pose. The EPA has recently revised regulations related to lead or galvanized steel pipes used for drinking water. A segment of that change requires water purveyors to research and document the pipe material types that are installed on both sides of the water meter. The Association has records that describe most service materials installed to the meter as that is where our jurisdiction ends. However, the Association has virtually no information on the member's private service line downstream of the meter.

If you have been involved in the modification or replacement of your private service line or have any information that you can provide to us about your service line, it will help reduce the overall cost to our membership as your Association works to comply with this new regulation.

Please fill out any/all information you may know below related to your private service line and return it to us. This could be enclosed with your residential water payment or sent separately. If you would rather speak with us directly to relay the requested information or have questions, please call the office at (360) 568-8022. We appreciate your cooperation in assisting us with this federal requirement.

-Three Lakes Water Association

Account number: _____

Shareholder's name(s): _____

Private service line installation date: _____

Private service line material: _____

Private service line size: _____

Any other information: _____

Location Information		System-Owned Portion							Customer-Owned Portion							Entire Service Line Material Classification
Location Identifier	System-Owned Portion Service Line Material Classification	If Non-Lead in Column G, Was Material Ever Previously Lead?	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material Was Field Verified:		Customer-Owned Portion Service Line Material Classification	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material Was Field Verified:		
Street Address	Dropdown list includes recommended subclassifications. If "Non-Lead Other", describe in Notes field	Select Yes, No, or Don't know. Important for determining if downstream/customer-owned galvanized service line requires replacement	Date, year, or estimated date range when the service line was installed or replaced	Diameter in inches	Select option from dropdown list. If "Other", describe in the Notes field	Select Yes or No	Select option from dropdown list. If "Other", describe in the Notes field	Enter approximate date of field verification or date that the record was updated	Dropdown list includes recommended subclassifications. If non-lead other, describe in Notes field.	Date, year, or estimated date range when the service line was installed or replaced	Diameter in inches	Select option from dropdown list. If "Other", describe in the Notes field	Select Yes or No	Select option from dropdown list. If "Other", describe in the Notes field	Enter approximate date of field verification or date that record was updated	
<small>Water systems must track addresses of all service lines in their internal inventory. For the publicly accessible version, location identifiers are required for lead and galvanized requiring replacement. If the system does not use addresses for their location identifier, other options could include GIS</small>																Dropdown list includes four required service line classifications of Lead, Non-lead, Galvanized Requiring Replacement, or Unknown
6316 151st Ave SE, Snohomish, WA 98290	Non-Lead - Copper	No	1964	3/4	Installation record (e.g., tap card)	No			Unknown - Material Unknown				No			Unknown
6319 151st Ave SE, Snohomish, WA 98290	Non-Lead - Copper	No	1964	3/4	Installation record (e.g., tap card)	No			Unknown - Material Unknown				No			Unknown
6429 151st Ave SE, Snohomish, WA 98290	Non-Lead - Copper	No	1964	3/4	Installation record (e.g., tap card)	No			Non-Lead - Plastic			Field inspection only with no records	Yes	Mechanical excavation at one location	9/26/2023	Non-Lead
6226 151st Ave SE, Snohomish, WA 98290	Non-Lead - Copper	No	1972	3/4	Installation record (e.g., tap card)	No			Unknown - Material Unknown				No			Unknown
6515 151st Ave SE, Snohomish, WA 98290	Non-Lead - Copper	No	1977	3/4	Installation record (e.g., tap card)	No			Unknown - Material Unknown				No			Unknown
6330 151st Ave SE, Snohomish, WA 98290	Non-Lead - Copper	No	1979	3/4	Installation record (e.g., tap card)	No			Unknown - Material Unknown				No			Unknown
6326 151st Ave SE, Snohomish, WA 98290	Non-Lead - Other	No	1990	3/4	Installation date after lead ban	No			Non-Lead - Other			Installation date after lead ban	No			Non-Lead
6424 151st Ave SE, Snohomish, WA 98290	Non-Lead - Copper	No	1990	3/4	Installation record (e.g., tap card)	No			Non-Lead - Other			Installation date after lead ban	No			Non-Lead
6324 151st Ave SE, Snohomish, WA 98290	Non-Lead - Other	No	1992	3/4	Installation date after lead ban	No			Non-Lead - Other			Installation date after lead ban	No			Non-Lead
6102 151st Ave SE, Snohomish, WA 98290	Non-Lead - Copper	No	1997	3/4	Installation record (e.g., tap card)	No			Non-Lead - Other			Installation date after lead ban	No			Non-Lead
6328 151st Ave SE, Snohomish, WA 98290	Non-Lead - Copper	No	1998	1	Installation record (e.g., tap card)	No			Non-Lead - Other			Installation date after lead ban	No			Non-Lead
6532 151st Ave SE, Snohomish, WA 98290	Non-Lead - Copper	No	2007	3/4	Installation record (e.g., tap card)	No			Non-Lead - Other			Installation date after lead ban	No			Non-Lead
6520 151st Ave SE, Snohomish, WA 98290	Non-Lead - Copper	No	2013	1	Installation record (e.g., tap card)	No			Non-Lead - Other			Installation date after lead ban	No			Non-Lead
6724 153rd Ave SE, Snohomish, WA 98290	Non-Lead - Copper	No	2014	1	Installation record (e.g., tap card)	No			Non-Lead - Other			Installation date after lead ban	No			Non-Lead
6830 153rd Ave SE, Snohomish, WA 98290	Non-Lead - Copper	No	2016	3/4	Installation record (e.g., tap card)	Yes	Mechanical excavation at one location	9/1/2019	Non-Lead - Other			Installation date after lead ban	No			Non-Lead
6210 157th Ave SE, Snohomish, WA 98290	Non-Lead - Copper	No	1964	3/4	Installation record (e.g., tap card)	No			Unknown - Material Unknown				No			Unknown
6127 157th Ave SE, Snohomish, WA 98290	Non-Lead - Copper	No	1964	3/4	Installation record (e.g., tap card)	No			Unknown - Material Unknown				No			Unknown
6011 157th Ave SE, Snohomish, WA 98290	Non-Lead - Copper	No	1976	3/4	Installation record (e.g., tap card)	No			Unknown - Material Unknown				No			Unknown
6410 157th Ave SE, Snohomish, WA 98290	Non-Lead - Copper	No	1978	3/4	Installation record (e.g., tap card)	No			Unknown - Material Unknown				No			Unknown
6430 157th Ave SE, Snohomish, WA 98290	Non-Lead - Copper	No	1980	3/4	Installation record (e.g., tap card)	No			Unknown - Material Unknown				No			Unknown
4621 157th Ave SE, Snohomish, WA 98290	Non-Lead - Copper	No	1982	3/4	Installation record (e.g., tap card)	No			Unknown - Material Unknown				No			Unknown
4519 157th Ave SE, Snohomish, WA 98290	Non-Lead - Copper	No	1982	3/4	Installation record (e.g., tap card)	No			Unknown - Material Unknown				No			Unknown
4722 157th Ave SE, Snohomish, WA 98290	Non-Lead - Copper	No	1983	3/4	Installation record (e.g., tap card)	No			Unknown - Material Unknown				No			Unknown
4418 157th Ave SE, Snohomish, WA 98290	Non-Lead - Copper	No	1983	3/4	Installation record (e.g., tap card)	No			Unknown - Material Unknown				No			Unknown
4910 157th Ave SE, Snohomish, WA 98290	Non-Lead - Plastic	No	1987	3/4	Installation record (e.g., tap card)	No			Non-Lead - Copper	1987	1	Other	No	Customer self-identification	1/22/2024	Non-Lead
4723 157th Ave SE, Snohomish, WA 98290	Non-Lead - Other	No	1988	3/4	Installation date after lead ban	No			Non-Lead - Plastic		1 1/4	Field inspection only with no records	Yes	Mechanical excavation at one location	9/21/2021	Non-Lead
4520 157th Ave SE, Snohomish, WA 98290	Non-Lead - Other	No	1989	3/4	Installation date after lead ban	No			Non-Lead - Other			Installation date after lead ban	No			Non-Lead
4917 157th Ave SE, Snohomish, WA 98290	Non-Lead - Other	No	1990	3/4	Installation date after lead ban	No			Non-Lead - Other			Installation date after lead ban	No			Non-Lead
4415 157th Ave SE, Snohomish, WA 98290	Non-Lead - Other	No	1990	3/4	Installation date after lead ban	No			Non-Lead - Other			Installation date after lead ban	No			Non-Lead
5014 157th Ave SE, Snohomish, WA 98290	Non-Lead - Other	No	1990	3/4	Installation date after lead ban	No			Non-Lead - Other			Installation date after lead ban	No			Non-Lead
6211 157th Ave SE, Snohomish, WA 98290	Non-Lead - Other	No	1990	3/4	Installation date after lead ban	No			Non-Lead - Other			Installation date after lead ban	No			Non-Lead
6330 157th Ave SE, Snohomish, WA 98290	Non-Lead - Copper	No	1991	3/4	Installation record (e.g., tap card)	No			Non-Lead - Plastic			Field inspection only with no records	Yes	Mechanical excavation at one location	6/1/2017	Non-Lead
4818 157th Ave SE, Snohomish, WA 98290	Non-Lead - Other	No	1992	3/4	Installation date after lead ban	No			Non-Lead - Other			Installation date after lead ban	No			Non-Lead
6326 157th Ave SE, Snohomish, WA 98290	Non-Lead - Other	No	1992	3/4	Installation date after lead ban	No			Non-Lead - Other			Installation date after lead ban	No			Non-Lead
4805 157th Ave SE, Snohomish, WA 98290	Non-Lead - Other	No	1993	3/4	Installation date after lead ban	No			Non-Lead - Other			Installation date after lead ban	No			Non-Lead
4616 157th Ave SE, Snohomish, WA 98290	Non-Lead - Copper	No	1997	3/4	Installation record (e.g., tap card)	No			Non-Lead - Other			Installation date after lead ban	No			Non-Lead
6406 157th Ave SE, Snohomish, WA 98290	Non-Lead - Copper	No	2006	3/4	Installation record (e.g., tap card)	No			Non-Lead - Other			Installation date after lead ban	No			Non-Lead
6413 157th Ave SE, Snohomish, WA 98290	Non-Lead - Copper	No	2016	1	Installation record (e.g., tap card)	Yes	Mechanical excavation at one location	6/16/2016	Non-Lead - Other			Installation date after lead ban	No			Non-Lead
5610 159th Ave SE, Snohomish, WA 98290	Non-Lead - Copper	No	2015	3/4	Installation record (e.g., tap card)	Yes	Mechanical excavation at one location	6/5/2015	Non-Lead - Other			Installation date after lead ban	No			Non-Lead
5606 159th Ave SE, Snohomish, WA 98290	Non-Lead - Copper	No	2015	3/4	Installation record (e.g., tap card)	Yes	Mechanical excavation at one location	6/5/2015	Non-Lead - Other			Installation date after lead ban	No			Non-Lead

5910 WONDERLAND RD, Snohomish, WA 98290	Non-Lead - Copper	No	1964	3/4	Installation record (e.g., tap card)	No			Unknown - Material Unknown			No			Unknown	
5722 WONDERLAND RD, Snohomish, WA 98290	Non-Lead - Copper	No	1964	3/4	Installation record (e.g., tap card)	No			Unknown - Material Unknown			No			Unknown	
5606 WONDERLAND RD, Snohomish, WA 98290	Non-Lead - Copper	No	1964	3/4	Installation record (e.g., tap card)	No			Non-Lead - Plastic	2013	1 1/4	Other	No	Customer self-identification	7/25/2023	Non-Lead
5320 WONDERLAND RD, Snohomish, WA 98290	Non-Lead - Copper	No	1964	3/4	Installation record (e.g., tap card)	No			Unknown - Material Unknown				No		Unknown	
5712 WONDERLAND RD, Snohomish, WA 98290	Non-Lead - Copper	No	1964	3/4	Installation record (e.g., tap card)	No			Unknown - Material Unknown				No		Unknown	
5812 WONDERLAND RD, Snohomish, WA 98290	Non-Lead - Copper	No	1965	3/4	Installation record (e.g., tap card)	No			Non-Lead - Plastic		1	Other	No	Customer self-identification	9/15/2023	Non-Lead
5310 WONDERLAND RD, Snohomish, WA 98290	Non-Lead - Copper	No	1966	3/4	Service line repair or replacement record	Yes	Mechanical excavation at one location	11/24/2021	Non-Lead - Plastic			Field inspection only with no records	Yes	Mechanical excavation at one location	11/24/2021	Non-Lead
5916 WONDERLAND RD, Snohomish, WA 98290	Non-Lead - Copper	No	1967	3/4	Installation record (e.g., tap card)	No			Non-Lead - Plastic			Field inspection only with no records	Yes	Mechanical excavation at one location	5/19/2023	Non-Lead
5625 WONDERLAND RD, Snohomish, WA 98290	Non-Lead - Copper	No	1968	1	Service line repair or replacement record	No			Non-Lead - Plastic			Field inspection only with no records	No		Non-Lead	
5702 WONDERLAND RD, Snohomish, WA 98290	Non-Lead - Copper	No	1971	3/4	Installation record (e.g., tap card)	No			Unknown - Material Unknown				No		Unknown	
5802 WONDERLAND RD, Snohomish, WA 98290	Non-Lead - Copper	No	1973	3/4	Installation record (e.g., tap card)	No			Unknown - Material Unknown				No		Unknown	
5820 WONDERLAND RD, Snohomish, WA 98290	Non-Lead - Copper	No	1975	3/4	Installation record (e.g., tap card)	No			Non-Lead - Plastic	2021		Field inspection only with no records	Yes	Mechanical excavation at one location	4/1/2023	Non-Lead
5428 WONDERLAND RD, Snohomish, WA 98290	Non-Lead - Plastic	No	1977	3/4	Installation record (e.g., tap card)	No			Non-Lead - Plastic			Field inspection only with no records	No		Non-Lead	
5616 WONDERLAND RD, Snohomish, WA 98290	Non-Lead - Copper	No	1989	1	Installation record (e.g., tap card)	No			Non-Lead - Other			Installation date after lead ban	No		Non-Lead	
5420 WONDERLAND RD, Snohomish, WA 98290	Non-Lead - Plastic	No	1990	3/4	Installation record (e.g., tap card)	No			Non-Lead - Plastic			Field inspection only with no records	No		Non-Lead	
5810 WONDERLAND RD, Snohomish, WA 98290	Non-Lead - Other	No	1992	3/4	Installation date after lead ban	No			Non-Lead - Other			Installation date after lead ban	No		Non-Lead	
5805 WONDERLAND RD, Snohomish, WA 98290	Non-Lead - Copper	No	2000	3/4	Installation record (e.g., tap card)	No			Non-Lead - Plastic			Installation record (e.g., tap card)	No		Non-Lead	
5522 WONDERLAND RD, Snohomish, WA 98290	Non-Lead - Copper	No	2021	1	Installation record (e.g., tap card)	Yes	Mechanical excavation at one location	3/4/2021	Non-Lead - Plastic			Field inspection only with no records	Yes	Mechanical excavation at one location	3/4/2021	Non-Lead